



CoFC

Attorney Docket No. 392.1856

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Osamu SAITO, et al.

Application No.: 10/749,374

ATTENTION

Confirmation No.: 9161

CERTIFICATE OF CORRECTION

Filed: January 2, 2004

BRANCH

Certificate

U.S. Patent No.: 6,904,819

JAN 30 2006

Issued: June 14, 2005

of Correction

For: MONITOR FOR INJECTION MOLDING MACHINE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Jan. 23, 2006

By: H.J. Staas
H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

JAN 31 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,904,819

DATED : June 14, 2005

INVENTOR(S) : Osamu SAITO, et al.

Column 2, line 23, after "variables" insert --,--.

Column 10, line 62, change "back pressure" to --backpressure--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,904,819

No. of add'l copies
@ 50¢ per page



JAN 31 2006